

**FLUKE**

**Hart Scientific**



# The care and maintenance of Standard Platinum Resistance Thermometers, SPRTs

Written by  
Steve Iman  
Fluke's Hart Scientific Division

Presented by  
Norman Willgress  
Fluke's Hart Scientific Division

# Agenda

- Introduction
- SPRT Construction
- Mechanical Treatment
- Thermal Treatment
- Maintenance
- Transportation

# Introduction

- Standard Platinum Resistance Thermometers (SPRTs) are the workhorse of modern temperature calibration
  - Cover  $-260^{\circ}\text{C}$  to  $960^{\circ}\text{C}$
  - Accuracies approaching 1 mK
  - If properly maintained offer years of service



# SPRT Construction

- High purity platinum wire
  - Diameter depends upon temperature range and nominal resistance value
  - Platinum wire is further heat treated to burn off remaining contaminants and anneal wire
- Strain-free coil is placed upon either quartz (preferred) or mica cross frame support
  - All material needs to be very clean to prevent contamination
  - Careful selection of materials also provides protection against contamination at high temperatures



# Gas mixture and sealing critical to long life

**FLUKE**

**Hart Scientific**

- The gas mixture inside of the SPRT is critical to long term stability
  - Balanced between preventing oxidation and contamination
- Seal construction critical to maintain solid barrier to atmosphere throughout a wide temperature range
  - At Hart our platinum leads exit through 7 different layers of fused silica glass to effectively match the expansion coefficient of platinum wire



# Mechanical treatment

- SPRTs sensing element is fragile
  - Metal sheath does not provide any better mechanical protection than fused silica sheath
- Even if damage isn't visible (examples to the right are extreme) accumulation of shock and vibration effects over time can significantly change  $R_{tpw}$  value
  - A change of 0.1 milliohms will cause a 1 mK in temperature for a 25 ohm SPRT




**This sensor was damaged by shock during shipping and handling**



**This sensor was damaged by vibration. Notice shorting of coils.**

# Thermal treatment

- Cleanliness is important!
  - Always clean SPRT with ethanol before using above 100°C
  - Devitrification is caused by contamination of the fused silica causing the sheath to become brittle and gas permeable
  - A human fingerprint will accelerate the devitrification process
- Never move an SPRT from a high temperature heat source directly into room air
  - Above 480°C SPRTs should be carefully cooled at a rate of 150°C per hour
- Keep the SPRT handle cool
  - High temperature damages the seal, cable insulation and solder connections



Devitrification of fused silica tube

# Hart SPRT max temperature

Hart Model Number	Maximum Temperature
5680, 5682, 5683	480°C
5681, 5698, 5699	670°C
5684, 5685	1070°C

**Never subject SPRT to temperatures above the manufacturers maximum specification!**



# Maintenance

- SPRTs like any piece of sensitive equipment requires periodic maintenance
- Maintenance consists of
  - Regular assurance tests to ensure confidence in operation
  - Periodic calibration
  - Cautious annealing

# Assurance testing

- Depending upon usage and application resistance tests at the TPW point are important to determining performance and maintenance tasks
  - Control charts or records should be maintained
  - Always use most recent Rtpw value for best accuracy
- Offset generally linear
  - Gallium / RTPW ratio  $\geq 1.1187$

# Ideal SPRT control chart





Figure 6

- SPRT  $R_{tpw}$  data should appear random
- As long as data falls within  $\pm 0.003^{\circ}\text{C}$  the SPRT should not need annealing

# Control chart showing contamination


**FLUKE**

Hart Scientific



- Steady upward trend is indicative of contamination, oxidation or severe mechanical shock occurring during usage

# Control chart showing seal failure




- Downward drift is indicative of a faulty seal allowing condensation to collect on the sensor reducing resistance – note the short time scale in chart above

# Control chart showing mechanical failure

FLUKE®

Hart Scientific




- Erratic Rtpw values are the result of coils touching, broken or loose wiring or Pt grain growth
- Often a slight tap on the handle will cause readings to jump

# Control chart showing annealing correction

FLUKE

Hart Scientific

Probe  
annealed



# Why anneal?

- Normal usage subjects SPRT to vibration which induces strain on the sensor which changes the resistance
- Heating and cooling an SPRT will trap point defects in the crystalline structure of the sensor changing resistance
- Between -40°C and 300°C a surface of platinum oxide (PtO<sub>2</sub>) forms on the surface of the sensor wire – 0.5 mK/hr
- Between -300°C and 500°C the body of platinum wire is oxidised – several mK per hour
- Supplemental ITS-90 – if SPRT used above 700°C always anneal before low temperature measurements, especially RTPW.

**Annealing will help correct all of these issues and bring the nominal Rtpw back closer to its original value**



# Recommend annealing temperatures for Hart SPRTs

**FLUKE**

Hart Scientific

Hart Model	Annealing Temp*	Time
5680, 5682, 5683	480°C	2 hours
5681, 5698, 5699	670°C	2 hours
5684, 5685	700°C	2 hours

\*Annealing temperature should be based upon the highest temperature point used when the SPRT was calibrated. For example if the highest point used to calibrate the SPRT was Zinc (419°C), then the annealing temperature should be 480°C

# Annealing furnace

- The proper selection of an annealing furnace is critical
- At annealing temperatures sensor contamination from the furnace material is likely
  - Metal and ceramic furnace material should not be used
- Temperature uniformity and stability in the zone where the sensor is located is important
- Being able to set the temperature ramp rate is very useful for safe heating and cooling of the SPRT



# Annealing procedure based upon NIST research

**FLUKE**

Hart Scientific

Range of SPRT Use	Procedure
Up to Zinc Point (419.527°C)	Hold at 450°C to 480°C for 4 hours
Up to Aluminum Point (660.323°C)	Thoroughly clean Heat from 500°C to 670°C 1 hour Hold at 670°C – 1.5 hours Cool to 500°C – 3 hours Remove to room temperature
Up to Silver Point (961.78°C)	Measure Rtpw for baseline Thoroughly clean Heat to 970°C – 2 hours Hold at 970°C – 1 hour Cool to 500°C – 4 hours Remove to room temperature

# Transportation

- Hand carrying is advisable to guarantee calibration integrity
- Hand carrying is not often possible over long distances
  - In this case a suitable container is required
    - Soft material to protect against shock and vibration
    - Large enough to provide space around the SPRT
  - Express or shipment by Air often provides better handling


# Hart's SPRT carrying case



# Carrying case inside of shipping container

**FLUKE**

Hart Scientific



# Summary

- SPRTs are excellent standards for the precise measurement of temperature
- Careful construction and handling ensures good performance for a long time
- Periodic maintenance and testing is important to guarantee the performance of your SPRT

