Fluke 713 Features at a Glance



Measure pressure, 0.05% of full scale
Measure mA, 0.025%
Calibrate I/P transmitter with simultaneous
pressure and current measurement
Select eleven different engineering units
Compatible with non-corrosive gases and liquids
Zero, min, max, hold functions
1/8 NPT female pressure fitting
Two shrouded banana jacks